

## 1976 SURVEY

On 24 July 1976, the Bloomington Cemetery was surveyed by Lotwick I. Reese, a licensed professional engineer in the State of Idaho. The survey was established by locating the center line of the east-west roadways, referenced from the iron pipe markers placed by the original survey in the sagebrush west of the Cemetery.

Selected corners of the cemetery were then surveyed and 23 permanent concrete markers were installed for future reference. Later steel posts were driven next to the concrete markers for easy reference, especially in the winter months. Mr. Reese surveyed and designated gravesites at the **top west portion** of the cemetery beginning from A2 to A9 across the top and then from 1 to 108.

The corners were established so that any lot in the cemetery could be measured with a 100 foot tape or chain.

Karel Thomas - board chairman      Paul Haddock – board member      T.Jay Nelson – board member

## 2016 SURVEY

On 18 July 2016, Lotwick I. Reese, licensed professional engineer in the State of Idaho, returned to the Bloomington Cemetery and surveyed the **lower east portion** of the cemetery.

At the time of this survey, Mr. Reese started surveying lots 109 to 153. He purposely lengthened these lots to accommodate the vaults that are now being used to hold and protect the caskets.

Permanent concrete markers were also installed for future reference. In addition, steel posts were driven next to the concrete markers for easier reference.

Mark F. Wilson – board chairman      Edward Payne – Sexton & board member  
Marcia Wilson – secretary & board member      Wayne Lloyd – board member  
Jolene Lloyd – board member